RICOH

Technical Bulletin

PAGE: 1/16

Updated: 30th June 2006: *Changes in bold italics*

Model: Martini-C2				Date: 21-Dec-04		No.: RB140000e	
Subject: Troubleshooting					Prepared by: S.Watanabe		
From: 1st Tech. Support Sec. Service Support Dept.							
Classification:		☐ Part info	orma	tion	☐ Action	n required	
		☐ Electric	al		☐ Service	ce manual revision	
	☐ Paper path	☐ Transm	it/rec	eive	Retro	fit information	
	Other ()						

This bulletin is a troubleshooting guide for symptoms that have occurred in the past, all with known solutions. For most items below, there are related MBs and RTBs containing modification details and adjustment procedures.

Note: This RTB is numbered "000" since the information contained in it has already been announced.

RICOH

Technical Bulletin

PAGE: 2/16

Updated: 30th June 2006: *Changes in bold italics*

Model: Martini-C2	Date: 21-Dec-04	No.: RB140000e
-------------------	-----------------	----------------

Ta	able of contents
1.	Paper feed problems
2.	Optional units
3.	Connectivity
4.	Printing
5.	Document server

RICOH

Technical Bulletin

PAGE: 3/16

Updated: 30th June 2006: Changes in bold italics

odel: Martini-C2	Date: 21-Dec-04	No.: RB140000e
New user account creation Disallowed login is possible Authentication screen not shown Authentication failure User name not assigned to scanned document Windows Authentication SSL/TLS		12
SC Codes and Error Messages 542, 545, 672 , 870, 990, 991 Remote firmware update error message		13
Image Quality Incorrect image rotation		14
Scanning The scanner stalls Compression error		14
Summer time does not function Service Mode Lock Operation panel freezes Counters Incorrect error message Machine freezes Machine settings are reset Incorrect wording Operation is too slow Incorrect wording		14
	New user account creation Disallowed login is possible Authentication screen not shown Authentication failure User name not assigned to scanned document Windows Authentication SSL/TLS User name and password already in login so SC Codes and Error Messages 542, 545, 672, 870, 990, 991 Remote firmware update error message Image Quality Incorrect image rotation Scanning The scanner stalls Compression error Others Summer time does not function Service Mode Lock Operation panel freezes Counters Incorrect error message Machine freezes Machine settings are reset Incorrect wording Operation is too slow	Security New user account creation Disallowed login is possible Authentication screen not shown Authentication failure User name not assigned to scanned document Windows Authentication SSL/TLS User name and password already in login screen SC Codes and Error Messages 542, 545, 672, 870, 990, 991 Remote firmware update error message Image Quality



PAGE: 4/16

Updated: 30th June 2006: Changes in bold italics

Model: Martini-C2 Date: 21-Dec-04 No.: RB140000e

1. Paper feed problems

Subject	Symptom	RTB#	Cause	Solution	Note
Jam 157	When the machine feeds LG	B140	Engine	Install the latest engine	Ver. 5.17 or
	paper from Tray 3	001a	firmware	firmware.	later
Jam 10	When the machine continuously feeds DTL paper from Tray 3 and LT from Tray 2	B140 001a	Engine firmware	Install the latest engine firmware.	Ver. 5.17 or later
Tab		B140	Engine	Install the latest engine	Ver. 5.20a or
sheet		001b	firmware	firmware.	later
paper					

2. Optional units

Subject	Symptom	RTB#	Cause	Solution	Note
Short-	Short-circuit in the stapler	B064	Harness rubs	Attach insulating tape to	
circuit	harness (SR850, SR860)	046	against rear plate	rear plate.	
LCT does	RT43 does not work on	B140	Produced before	Install an RT43 made in	
not work	MT-C2a or MT-C2b	021	Aug 2004	Aug 2004 or later. If not	
				possible, replace the	
				EPROM in the finisher.	
Finisher	SR841 does not work on	B140	Produced before	Install an SR841 made	
does not	MT-C2a or MT-C2b	014	Sept 2004	in Sept 2004 or later. If	
work				not possible, replace the	
				EPROM in the finisher.	
Finisher	SR850 does not work on	B140	Produced before	Install an SR850 made	
does not	MT-C2a or MT-C2b	022a	Jan 2004	in Jan 2004 or later. If	
work				not possible, replace the	
				EPROM in the finisher.	
Finisher	If both the Plockmatic and	B140	System/Copy	Install the latest	Ver. 1.16.1
does not	Victoria finisher are	002c	firmware	system/copy firmware	or later
work	installed, the Victoria				
	finisher will not be				
	available for printing. This				
	is caused by an MIB error.				



PAGE: 5/16

Updated: 30th June 2006: *Changes in bold italics*

Model: Martini-C2 Date: 21-Dec-04 No.: RB140000e

3. Connectivity

Subject	Symptom	RTB#	Cause	Solution	Note
Smart Device Monitor for Admin	Cannot use "Address Management Tool" or "User Management Tool".	B140 020a	Incorrect setting for "Permit Simple Encryption"	Change the setting of the "Permit Simple encryption" user tool to ON at machine installation.	
Smart Device Monitor for Admin	This application does not work if address book encryption is used.	B140 006a	Netfile firmware	Install the latest Netfile firmware	Ver. 0.34.1 or later
Smart Device Monitor for Admin	The Folder authentication setting in the address book cannot be changed to "Do not specify" using the SDM Address Management Tool.	B140 006b	Netfile firmware	Install the latest Netfile firmware	Ver. 0.40 or later
Smart Device Monitor for Admin	If 2-byte characters are input for Name/Key Display using the SDM Address Management Tool, these characters will be displayed on the machine's operation panel as the ASCII representations of the single-byte values.	B140 006b	Netfile firmware	Install the latest Netfile firmware	Ver. 0.40 or later
Smart Device Monitor for Admin	SDM for Admin, running on a client PC that is connected to both a 1394 and an Ethernet interface cannot retrieve the 1394 hostnames of machines.	B140 003c	NCS (NIB) firmware	Install the latest NCS firmware When installing ver. 4.17, it is necessary to install Websys ver. 1.04 and System ver. 1.19.1 together as a set.	Ver. 4.17 or later
Smart Device Monitor for Admin	If multiple PCs access the machine at the same time, cannot configure the machine with SDM Admin's "User Management Tool".	B140 006c	Netfile firmware	Install the latest Netfile firmware	Ver. 1.00 or later
Smart Device Monitor for Admin	Cannot access the machine with SDM for Admin after "Permit Simple Encryption" in Extended Security is disabled.	B140 006c	Netfile firmware	Install the latest Netfile firmware	Ver. 1.00 or later
Smart Device Monitor	Address book not updated properly	011d	DESS firmware	Install new DESS firmware	Ver 3.07 or later



PAGE: 6/16

Updated: 30th June 2006: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Scan Router	Cannot login to the MT-C2 when trying to add MT-C2 to the "I/O device list".	B140 020a	Incorrect setting for "Permit Simple Encryption"	Change the setting of the "Permit Simple encryption" user tool to ON at machine installation.	
Scan Router	Cannot add devices	B140 006a	Netfile firmware	Install the latest Netfile firmware	Ver. 0.34.1 or later
Scan Router	Cannot send files to a user's folder for a user that was registered with 'Printer: PC Control'. The file goes to the default folder.	B140 009c	Printer firmware	Install the latest Printer firmware	Ver. 1.02 or later
Scan Router	Multiple page documents scanned with the single-page PDF setting will be sent to the ScanRouter server as multiple TIFF files.	B140 010c	Scanner firmware	Install the latest Scanner firmware	Ver. 1.07 or later
Desk Top Binder	Cannot login to the MT-C2 when trying to use the "Document Server:Authentication" Encryption" function.	B140 020a	Incorrect setting for "Permit Simple Encryption"	Change the setting of the "Permit Simple encryption" user tool to ON at machine installation.	
Desk Top Binder	If multiple PCs are accessing the machine at the same time, cannot use Desk Top Binder to send scanned files from the Document Server to a server such as ScanRouter.	B140 006c	Netfile firmware	Install the latest Netfile firmware	Ver. 1.00 or later
Address book	If the address book is backed-up and then restored with the Address Management Tool in SDM for Admin, some items will be returned to their default values:	B140 002c	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.16.1 or later
Address book	If restoration of the address book fails, an error message will be shown. But if the restoration is attempted again, the error message will not be shown.	B140 002c	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.16.1 or later



PAGE: 7/16

Updated: 30th June 2006: *Changes in bold italics*

Subject	Symptom	RTB#	Cause	Solution	Note
Address	Some data not	B140	System/Copy	Install the latest	Ver. 1.17 or
	transferred to the	002e	firmware	system/copy firmware	later
	address book when the				
	user logs in with				
	Windows				
	Authentication	D440	0 1 10	Landall dia a lada at) / a a d d 0 d
	Incorrect MIB data for	B140	System/Copy	Install the latest	Ver. 1.16.1
	the LCT May not connect using	002c B140	firmware NIB firmware	system/copy firmware Install the latest NIB	or later Ver. 4.08 or
IVIID/SINIVIP	SNMP v3 when a static	003a	INID IIIIIWale	firmware	later
	IP address is used.	003a		Illiliwale	latei
	SNMP may not start	B140	NCS (NIB)	Install the latest NCS	Ver. 4.17 or
	when the machine is	003c	firmware	firmware	later
	turned on. Utilities	0000	iiiiiiwaro	When installing ver.	lator
	using SNMP will not			4.17, it is necessary to	
	receive status updates			install Websys ver. 1.04	
	from the machine.			and System ver. 1.19.1	
				together as a set.	
MIB/SNMP	If a lot of SNMP traffic	B140	NCS (NIB)	Install the latest NCS	Ver. 4.17 or
	is sent to the device,	003c	firmware	firmware	later
	the SNMP buffer may			When installing ver.	
	become full. Then the			4.17, it is necessary to	
	machine cannot reply			install Websys ver. 1.04	
	to SNMP requests.			and System ver. 1.19.1	
A AUD (ON IN AD	ONINAD: 41. O a see de	D440	NOO (NID)	together as a set.	\/a= 4.47.a=
	SNMPv1/v2 sends	B140	NCS (NIB) firmware	Install the latest NCS	Ver. 4.17 or
	SNMP traps if SNMPv1/v2 is	003c	Illimware	firmware When installing ver.	later
	disabled.			4.17, it is necessary to	
	disabled.			install Websys ver. 1.04	
				and System ver. 1.19.1	
				together as a set.	
Cannot see	Cannot see other	B140	NIB firmware	Install the latest NIB	Ver. 4.08 or
	members of the	003a		firmware	later
	workgroup if the				
	workgroup name is 15				
	bytes				
	Only shown the first	B140	NIB firmware	Install the latest NIB	Ver. 4.08 or
	time the machine is	003a		firmware	later
	switched on after a				
	wireless LAN card is				
	installed.	B140	Netfile firmware	Install the latest Netfile	Vor 0 40 or
eCabinet	If the "Capture Server IP address" is changed	006b	ivetille littiware		Ver. 0.40 or
	manually to use the	JUUD		firmware	later
	eCabinet server as a				
	capture server, the				
	device must be				
	rebooted before it can				
	access the new IP				
	address.				
l l					



PAGE: 8/16

Updated: 30th June 2006: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
RCGate	Cannot update firmware with RCGate	B140 002g	System/Copy firmware	Install the latest system/copy firmware When installing ver. 1.19.1, it is necessary to install NCS ver. 4.17 and Websys ver. 1.04 together as a set.	Ver. 1.19.1 or later
Cannot login	If more than 128 login attempts are made from the operation panel in a single power cycle, the software keyboard will be unresponsive and users cannot login	B140 002g	System/Copy firmware	Install the latest system/copy firmware When installing ver. 1.19.1, it is necessary to install NCS ver. 4.17 and Websys ver. 1.04 together as a set.	Ver. 1.19.1 or later
Cannot login	If the machine gets more than 300 login attempts without cycling the power, SC991 appears and users cannot login	B140 002g	System/Copy firmware	Install the latest system/copy firmware When installing ver. 1.19.1, it is necessary to install NCS ver. 4.17 and Websys ver. 1.04 together as a set.	Ver. 1.19.1 or later
Cannot login	Users cannot login via Windows Authentication using a domain controller in a different subnet unless WINS is enabled.	B140 002g	System/Copy firmware	Install the latest system/copy firmware When installing ver. 1.19.1, it is necessary to install NCS ver. 4.17 and Websys ver. 1.04 together as a set.	Ver. 1.19.1 or later
Web Image Monitor	ROM update not shown in the menu	B140 002g	System/Copy firmware	Install the latest system/copy firmware When installing ver. 1.19.1, it is necessary to install NCS ver. 4.17 and Websys ver. 1.04 together as a set.	Ver. 1.19.1 or later
Web Image Monitor	If the paper type setting is changed via WIM while "Permit Settings by SNMPv1 and v2" is disabled, the browser will timeout. The paper type setting change will not be saved.	B140 003c	NCS (NIB) firmware	Install the latest NCS firmware When installing ver. 4.17, it is necessary to install Websys ver. 1.04 and System ver. 1.19.1 together as a set.	Ver. 4.17 or later
Web Image Monitor	No ROM update function in WIM	007d	WebSystem firmware	Install the latest WebSystem firmware When installing ver. 1.04, it is necessary to install NCS ver. 4.17 and System ver. 1.19.1 together as a set.	Ver. 1.04 or later



PAGE: 9/16

Updated: 30th June 2006: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Web Image Monitor	Incorrect wording (German, Czech)	007d	WebSystem firmware	Install the latest WebSystem firmware When installing ver. 1.04, it is necessary to install NCS ver. 4.17 and System ver. 1.19.1 together as a set.	Ver. 1.04 or later
Web Image Monitor	LDAP settings made with WIM are not effected (the settings work OK if input from the operation[panel]	007d	WebSystem firmware	Install the latest WebSystem firmware When installing ver. 1.04, it is necessary to install NCS ver. 4.17 and System ver. 1.19.1 together as a set.	Ver. 1.04 or later
Scan to Folder/Scan to e-mail	Scan to Folder and Scan to E-mail functions are grayed out.	010d	Scanner firmware	Install the latest scanner firmware	Ver. m2e_1.08 or later
Scan to Folder/Scan to e-mail	Connection test fails if folder name contains 2-byte fonts	B140 003c	NCS (NIB) firmware	Install the latest NCS firmware When installing ver. 4.17, it is necessary to install Websys ver. 1.04 and System ver. 1.19.1 together as a set.	Ver. 4.17 or later



PAGE: 10/16

Updated: 30th June 2006: Changes in bold italics

Model: Martini-C2 Date: 21-Dec-04 No.: RB140000e

4. Printing

Subject	Symptom	RTB#	Cause	Solution	Note
Print job	PC cannot connect to the	B140	System/Copy	Install the latest	Ver. 1.04.1
cancelled	printer; Windows	002b	firmware	system/copy firmware	or later
	Authentication is in use				
Print job	Cancelled if User	B140	Incorrect setting	Change the setting of	
cancelled	Authentication is enabled	020a	for "Permit Simple	the "Permit Simple	
	on the copier, and some		Encryption"	encryption" user tool to	
	other conditions are met			ON at machine	
5		D 4 4 0	D : (C	installation.	11/
Print job	PDF Direct Print jobs sent	B140	Printer firmware	Install the latest printer	Ver. 1.04 or
cancelled	via DeskTopBinder in	009e		firmware	later
	driverless mode, will be				
	cancelled if user code				
Cannot	authentication is enabled. If Windows Authentication	B140	Netfile firmware	Install the latest Netfile	Ver. 0.34.1
print	is enabled, printing with	006a	inetille liffiware	firmware	or later
print	Smart Device Monitor	000a		Illiliwale	Oi latei
	ports is not possible.				
Cannot	User Code Authentication	B140	Printer firmware	Install the latest printer	Ver. 1.01 or
print	enabled	009b		firmware	later
Cannot	After a power cycle, the	B140	NIB firmware	Install the latest NIB	Ver. 4.08.3
print	machine does not accept	003b		firmware	or later
	jobs from standard				
	TCP/IP or SDM ports.				
Cannot	If User Code	B140	Printer firmware	Install the latest Printer	Ver. 1.02 or
print	Authentication is enabled,	009c		firmware	later
	files stored locked print				
	and sample print cannot				
	be output				
Cannot	If multiple PCs access the	B140	Netfile firmware	Install the latest Netfile	Ver. 1.00 or
print	machine at the same time,	006c		firmware	later
	cannot print to a Smart				
	Device Monitor port.	D440	D00 f	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	11/ 4.04
Cannot	Some Thai and Latin	B140	PS3 firmware	Install the latest PS3	Ver. 1.01 or
print some	characters cannot be	012a		firmware	later
characters	printed with the PS driver	D440	Deinte of Green	Landall the Latent and t	1/22 4 04
Slow	When PCL data is printed	B140	Printer firmware	Install the latest printer	Ver. 1.04 or
printing	using fonts on the HDD	009e		firmware	later



PAGE: 11/16

Updated: 30th June 2006: Changes in bold italics

Model: Martini-C2 Date: 21-Dec-04 No.: RB140000e

5. Document server

Subject	Symptom	RTB#	Cause	Solution	Note
Cannot	Files that were originally	B140	System/Copy	Install the latest	Ver. 1.16.1
delete files	sent to the document	002c	firmware	system/copy firmware	or later
	server using the Copy				
	function.				
Cannot	Cannot print with	B140	Netfile firmware	Install the latest Netfile	Ver. 0.34.1
print files	DeskTopBinder Lite v4.	006a		firmware	or later
Download	Poor image quality of	B140	Netfile firmware	Install the latest Netfile	Ver. 0.34.1
problems	files downloaded with	006a		firmware	or later
	Desktop Editor for				
	Production				
Download	Incorrect file format for	B140	Netfile firmware	Install the latest Netfile	Ver. 0.34.1
problems	images downloaded with	006a		firmware	or later
	Desktop Editor for				
	Production	D440	N. (C) C		
Download	Cannot download with	B140	Netfile firmware	Install the latest Netfile	Ver. 0.34.1
problems	Web Image Monitor on a	006a		firmware	or later
Lining	Windows XP SP2 PC	D440	Nattila timesana	Lookall the clate of Nietfile	\/a= 0.40 a=
Upload	Documents downloaded	B140	Netfile firmware	Install the latest Netfile	Ver. 0.40 or
problems	from the document	006b		firmware	later
	server in J2K format via				
	the DeskTopEditor for Production cannot be				
	opened or uploaded to				
	the document server.				
Garbled	Garbled filenames or	B140	Netfile firmware	Install version 1.01 or	
filenames	user names when two-	006d	ivedile illiliwale	later.	
inenanes	byte characters are	JUUU		iatei.	
	used in the filename				
	used in the menanie				



PAGE: 12/16

Updated: 30th June 2006: *Changes in bold italics*

Model: Martini-C2 Date: 21-Dec-04 No.: RB140000e

6. Security

Subject	Symptom	RTB#	Cause	Solution	Note
New user account creation	Password registering routine does not work correctly; the administrator is not prompted to confirm the password that was input	B140 002c	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.16.1 or later
Disallowed login is possible	When "Permit Simple Encryption" is "OFF" and User Code Authentication is enabled, users will still be able to login using User Codes. This should not be possible.	B140 002c	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.16.1 or later
Authentication screen not shown	If user B tries to use the document server while user A scans a document with the TWAIN driver, the authentication screen is not shown for user B. This only happens if Basic Authentication is enabled.	B140 002c	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.16.1 or later
Authentication failure	Occurs if the windows password is 128 bytes	B140 003a	NIB firmware	Install the latest NIB firmware	Ver. 4.08 or later
User name not assigned to scanned document		B140 010a	Scanner firmware	Install the latest scanner firmware	Ver. 1.05 or later
Windows Authentication	Available functions cannot be restricted to groups via Windows Authentication using a domain controller in a different subnet.	B140 003c	NCS (NIB) firmware	Install the latest NCS firmware When installing ver. 4.17, it is necessary to install Websys ver. 1.04 and System ver. 1.19.1 together as a set.	Ver. 4.17 or later
SSL/TLS	Rollback vulnerability	B140 011e	DESS firmware	Install version 3.08 or later.	
User name and password already in login screen	When someone opens the login screen by pressing the User Tools button. This occurs if username and password are left in the field without logging in.	B140 002h	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.20 or later



PAGE: 13/16

Updated: 30th June 2006: Changes in bold italics

Model: Martini-C2 Date: 21-Dec-04 No.: RB140000e

7. SC codes

Subject	Symptom	RTB#	Cause	Solution	Note
SC542		B140 025	Thermostat was replaced incorrectly	Position the cable correctly, and tighten the screw fully	
SC545		B140 025	Thermostat was replaced incorrectly		
SC672	Occurs when multiple PCs access the Document Server using Web Image Monitor to download PDF files.	B140 006c	Netfile firmware	Install the latest Netfile firmware	Ver. 1.00 or later
SC672	When the main power is turned OFF/ON and performing the SC auto reboot function.	B140 002h	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.20 or later
SC870	Occurs during address book update	B140 002e	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.17 or later
SC870	Occurs after logout from a session, if two specific settings were changed during the session	B140 002f	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.18.1 or later
SC990	Occurs if the previous user logged out before files were printed fully	B140 002e	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.17 or later
SC990	Occurs when using the 'Program' function	B140 010a	Scanner firmware	Install the latest scanner firmware	Ver. 1.05 or later
SC991	If the devices receive more than 300 login attempts without cycling the power, SC991 appears and users cannot login	B140 002g	System/Copy firmware	Install the latest system/copy firmware When installing ver. 1.19.1, it is necessary to install NCS ver. 4.17 and Websys ver. 1.04 together as a set.	Ver. 1.19.1 or later
SC991	Occurs if a) 2 or more interfaces (e.g. Ethernet & IP over 1394) are communicating at the same time and b) the SMTP server registered in the machine doesn't exist.	B140 003a	NIB firmware	Install the latest NIB firmware	Ver. 4.08 or later
Remote firmware update error	Displayed when the update was successful	B140 002h	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.20 or later



PAGE: 14/16

Updated: 30th June 2006: *Changes in bold italics*

Model: Martini-C2 Date: 21-Dec-04 No.: RB140000e

8. Image Quality

Subject	Symptom	RTB#	Cause	Solution	Note
Incorrect image rotation	If a file is printed from the document server with the PCL driver and it has mixed page orientations with the first page Landscape	B140 009c	Printer firmware	Install the latest Printer firmware	Ver. 1.02 or later

9. Scanning

Subject	Symptom	RTB#	Cause	Solution	Note
Scanning stalls	TWAIN driver used	B140	Scanner	Install the latest scanner	Ver. 1.06 or
	repeatedly	010b	firmware	firmware	later
Compression	The grayscale	B140	Scanner	Install the latest scanner	Ver. 1.07 or
error	'Compression' setting in	010c	firmware	firmware	later
	the Scanner System is				
	wrong.				
	- Low compression				
	produces low-quality				
	images with high				
	compression.				
	- High compression				
	produces high-quality				
	images with low				
	compression.				

10. Others

Subject	Symptom	RTB#	Cause	Solution	Note
Summer	Does not work	B140	System/Copy	Install the latest	Ver. 1.03.2
time		002a	firmware	system/copy firmware	or later
Service	Cannot be disabled after	B140	System/Copy	Install the latest	Ver. 1.04.1
mode lock	an SC	002b	firmware	system/copy firmware	or later
Operation	Occurs if an LDAP	B140	System/Copy	Install the latest	Ver. 1.16.1
panel	search is canceled	002c	firmware	system/copy firmware	or later
freezes					
Operation	Occurs if address book	B140	System/Copy	Install the latest	Ver. 1.17 or
panel	encryption is cancelled	002e	firmware	system/copy firmware	later
freezes					
Counters	If documents with mixed	B140	System/Copy	Install the latest	Ver. 1.16.1
	sized pages are	002c	firmware	system/copy firmware	or later
	scanned and User				
	Authentication is on, the				
	"other" counter is				
	incremented instead of				
	the user's counter.				



PAGE: 15/16

Updated: 30th June 2006: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Incorrect	If someone tries to scan	B140	System/Copy	Install the latest	Ver. 1.16.1
error	using the TWAIN driver	002c	firmware	system/copy firmware	or later
message	while someone else is				
	logged into the machine,				
	an error message				
	appears. Then, if the				
	user tries to scan again				
	with the TWAIN driver				
	after the other user has				
	logged out, the message				
	will continue to be				
	shown.				
Incorrect	If someone tries to	B140	Netfile firmware	Install the latest Netfile	Ver. 0.34.1
error	restore the address	006a		firmware	or later
message	book with Smart Device				
	Monitor for Admin while				
	another user is using the address book				
Incorrect	The first time a user	B140	WebDocBox	Install the latest	Ver. 1.01 or
error	accesses a document	008a	firmware	WebDocBox firmware	later
message	after the access	000a	IIIIIIwaie	Webbocbox IIIIIware	iatei
message	privileges for this				
	document were changed				
Machine	If a lot of pages are	B140	System/Copy	Install the latest	Ver. 1.16.1
freezes	scanned with SADF	002c	firmware	system/copy firmware	or later
Machine	If restoration of the	B140	Netfile firmware	Install the latest Netfile	Ver. 0.34.1
freezes	address book with Smart	006a		firmware	or later
	Device Monitor for				
	Admin is not completed				
	properly				
Machine	Occurs after an error is	B140	Printer firmware	Install the latest Printer	Ver. 1.02 or
freezes	fixed (e.g., no paper),	009c		firmware	later
	then a stored document				
NA I- i	is printed	D440	Dainten finnen	Locate II the classest Deleter	1/ 4.00
Machine	Occurs after a one-page	B140	Printer firmware	Install the latest Printer	Ver. 1.02 or
freezes	job is printed with duplex	009c		firmware	later
Machine	mode Occurs if a duplex job	B140	Printer firmware	Install the latest Printer	Ver. 1.04 or
freezes	with the RPCS driver is	009e	i illiter lillilwale	firmware	later
1100203	cancelled	0000		minward	later
Machine	Occurs after a certain	B140	Printer firmware	Install the latest Printer	Ver. 1.04 or
freezes	number of PCL jobs are	009e		firmware	later
	printed using HDD fonts.				
Machine	If a job request is	B140	Engine firmware	Install the latest engine	Ver. 5.20a or
freezes	received from one of the	001b	_	firmware.	later
	other primary machine				
	functions while				
	performing a scanning				
	job.				
	1	<u> </u>		1	



PAGE: 16/16

Updated: 30th June 2006: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Machine freezes	During login, if the automatic logout confirmation was displayed 2 times after the Exit button was pressed in System Settings.	B140 002h	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.21 or later
Machine settings are reset	The "Blank page print" setting is lost if the machine power is turned off and then on	B140 009c	Printer firmware	Install the latest Printer firmware	Ver. 1.02 or later
Incorrect wording	A button is worded incorrectly in Russian	B140 010b	Scanner firmware	Install the latest Scanner firmware	Ver. 1.06 or later
Incorrect wording	Errors on the operation panel in multiple languages	B140 009d	Printer firmware	Install the latest Printer firmware	Ver. 1.03 or later
Operation is too slow	Document server menu displayed too slowly	B140 006c	Netfile firmware	Install the latest Netfile firmware	Ver. 1.00 or later
Incorrect wording	'Device Name' not translated in the Finnish language version of WIM.	007d	WebSystem firmware	Install the latest WebSystem firmware When installing ver. 1.04, it is necessary to install NCS ver. 4.17 and System ver. 1.19.1 together as a set.	Ver. 1.04 or later
Incorrect page numbering	Printing from the document server with the Magazine function	B140 002h	System/Copy firmware	Install the latest system/copy firmware	Ver. 1.20 or later